



**Dominion**

# DAM INSPECTION CHECKLIST POSSUM POINT POWER STATION POND ABC

INSPECTION DATE: FEB. 2, 2016

WEATHER: 50, PARTLY CLOUDY

INSPECTED BY: K. ACREE

Location/ Condition	(y/n)	Change (y/n)	Comments
Low Point, A dike*			
Flow	N	N	1523 -> SAND BAGS & RIGRAP IN PLACE, WITH SEVERAL SAND BAGS THAT ARE RIPPED
Erosion	N	N	NO STANDING WATER AGAINST SAND BAGS
Low Point, B dike*			
Flow	N	N	1528 -> SAND BAGS ARE IN PLACE AND SEVERAL SAND BAGS ARE RIPPED,
Erosion	N	N	NO STANDING WATER AGAINST SAND BAGS
Outfall water surface El. (top of stoplogs to water)			1533 -> NO STANDING WATER AGAINST WEIR, NO FLOW THROUGH WEIR, AND THE WEIR APPEARS TO BE DRY.

\* See figure below.

**Additional Comments (Note any changes observed along the embankment crest or downstream slope observed from the crest.):** - LOW POINT, (DIKE) SAND BAGS IN PLACE, SEVERAL SAND BAGS ARE RIPPED, AND THERE IS NO STANDING WATER AGAINST SAND BAGS  
- POND A HAS ~~water~~ <sup>STANDING</sup> WATER AT INSIDE TOE OF EMBANKMENT (TYPICAL OF PONDS B & C)  
- STANDING WATER AT TOP OF EMBANKMENT OF PONDS (AS NOTED BELOW)  
- ~~STANDING WATER AT TOP OF EMBANKMENT OF PONDS (AS NOTED BELOW)~~ KMA 2/3/16

